

The **CAS1040** with firmware **Version 6.00** does fix the MAC clone issue for cable Internet service and has added more features:

1. Static DHCP assignment
2. Dynamic DNS
3. IPSec pass through
4. Multicast pass through
5. Save user setting
6. Event log
7. Improve performance
8. Network time
9. Multi DMZ
10. DNS redirection

It has also solved the webpage downloading issue (ADSL Internet Service) in **Manitoba** area by adjusting the **Max. Packet Size (MSS) value**:

1. Using the Internet browser, such as Internet Explorer or Netscape, to access the router by entering 192.168.1.254 (Note: this is the only IP address that can access the web configuration).
2. Select **File/ Configuration/ Global Port /PPPoE** connection and choose the MSS **1360** or the best value you like.
3. Click **Save** and wait for 20 seconds to allow the router to save the configuration.