

The **CAS2040** with firmware **Version 6.03** has solved the MAC clone issue for cable Internet Service.

It has also solved the webpage downloading issue (ADSL Internet Service) in **Manitoba** area by adjusting the **Max. Packet Size (MSS) value**:

1. Using the Internet browser, such as Internet Explorer or Netscape, to access the router by entering 192.168.1.254 (Note: this is the only IP address that can access the web configuration).
2. Select **File/ Configuration/ Global Port /PPPoE** connection and choose the MSS **1360** or the best value you like.
3. Click **Save** and wait for 20 seconds to allow the router to save the configuration.